


110 589 02 63 00


Adjusting tool



**MODEL 124**

**i** The spray jet must hit the glass surface in the marked area.


P82.35-2023-01



**MODEL 129**

**i** The spray jet should hit the glass surface in the marked area.


P82.35-2020-01



**Model 140**

**i** The spray jet must hit the glass surface in the marked area.


P82.35-2019-01



**Model 168, 414 shown on model 168**

**i** The spray jet should hit the glass surface in the marked area.


P82.35-2021-01



**MODEL 170**

**i** The spray jet must hit the glass surface in the marked area.


P82.35-2022-01



**MODEL 202**


**i** The spray jet should hit the glass surface in the marked area.

P82.35-2026-01

1 Correct windshield washer system spray nozzle settings if necessary using  adjusting pin.

**i** The spray jet must hit the windshield in the marked area.

**Models 208, 210, shown on model 210**



P82.35-2024-01